F BIRV38 BSP*

Codice articolo: **800500102** / **?????** / ***Prodotto disponibile su richiesta**

??????? ?????????? ?????? (POPPET)	**?????? ??????????** 3/8"
?????????? FKM (VITON)	**?????????** Cr3
???????????????????? ISO 7241 A	**??????? ??????????** ????? ???????????? ???????? ? ??????
??????? ???????????? ????? ???????????? ????????	**????????** ????????????? ???????????? ?????
???????? ?????????? ????????????? ???	**???????????? ??? ?????????** ???
P????? FEMALE THREAD BSPP (ISO 1179-1)	**?????????? ? ?????????? ?????????** ???
??????????? -15 / +180 °C; +5 / +356 °F	**??????? ??????????** ????????????????????? ????????, ?????????????????????? ???????? ????????????, ???????? ???????????? ??? ???????????? ????????, ????????, ???????????? ??????, ??????????-???????????? ??????, ???????? ?????????????, ?????????????, ???????? ?????????

?????????????????????	IMPERIAL
ISO DN (mm)	10
???????????? ?????? (???/???)	12.19
???????????? ??????? ???????? - ?????????? (psi)	4350
??????? ???????? - ???????????? (????/??. ????)	4350
???????? ??????? - ????????? (????/??. ????)	14500
???????? ??????? - ???????????? (????/??. ????)	14500
???? ?????????? (???? ????)	20,25
???? ????????????? (???? ????)	6.75
?????? (??)	1.2

??????	IMPERIAL
?????? ??????? (A)	3/8"
????? ????? ?+? (????)	3,02
????? (????)	2,21
????????????? ??????? (????)	1,22
??? (????)	0,33

????????????? ???????

??? ????????	**Tipologia**	**???????????? ????????**
800500103	Maschio	M BIRV38 BSP

Spare kits

??? ????????	**???????????? ????????**
815700188	SPARE KIT OR VITON+BK F BIR38**

Caps

??? ????????	**???????????? ????????**
815000014	PLASTIC PLUG F ISO-A 38 RED

??????? ???????? ?? ???????

STUCCHI Quick Couplings Catalog - April 2021 - All right reserved.
Via della Lira Italiana, 397 24040 - Pagazzano (BG) Italy - Contact us
Texts, data and illustrations mentioned in this catalogue may be changed by Stucchi at any time, without notice; always refer to the version uploaded on the English version of stucchigroup.com/en website for the latest release. In case of doubt, please contact Stucchi technical service