M A15 1 BSP

Codice articolo: **801300035 / ???????**

??????? ?????????? ??????? ???????????	**?????? ??????????** 5/8"
?????????? Nitrile NBR	**?????????** Cr3
???????????????????? ISO 16028	**??????? ??????????** ??????
??????? ???????????? ????? ???????????? ????????	**????????** ????????????? ???????????? ?????
???????? ??????????? ????????????? ??? + ??????????	**???????????? ??? ?????????** ???
P????? FEMALE THREAD BSPP (ISO 1179-1)	**?????????? ? ?????????? ?????????** ???
?????????? -20 / +100 °C; -4 / +212 °F	**??????? ??????????** ?????????????, ???????? ?????????, ????????? ? ???????????? ????????, ????? ? ???

?????????????????	METRIC
ISO DN (mm)	16
???????????? ?????? (?/???)	148
???????????? ??????? ???????? - ?????????? (???)	33
??????? ???????? - ???????????? (???)	33
???????? ??????? - ????????? (???)	100
???????? ??????? - ???????????? (???)	100
???? ?????????? (?)	190
???? ????????????? (?)	55
?????? (??)	0.02

??????	METRIC
?????? ??????? (A)	1"
????? ????? ?+? (??)	145,4
????? (??)	76
???????????? ??????? (??)	27
??? (??)	0,33

????????????? ???????

??? ????????	Tipologia	???????????? ????????
801300034	Femmina	F A15 1 BSP

Spare kits

??? ????????	???????????? ????????
815700341	SPARE KIT OR NBR+BK M FF 58

Caps

??? ????????	???????????? ????????
815100011	PLASTIC CAP M FF58 RED
816005009	ALUMINUM CAP M FF58 NATURAL
815101011	PLASTIC CAP M FF58 YELLOW*
815102011	PLASTIC CAP M FF58 BLUE*
815103011	PLASTIC CAP M FF58 BLACK*
815104011	PLASTIC CAP M FF58 GREEN*
815105011	PLASTIC CAP M FF58 WHITE*
815107011	PLASTIC CAP M FF58 ORANGE*
815110011	PLASTIC CAP M FF58 MAGENTA*

*??????? ???????? ?? ???????

STUCCHI Quick Couplings Catalog - April 2021 - All right reserved.
Via della Lira Italiana, 397 24040 - Pagazzano (BG) Italy - Contact us
Texts, data and illustrations mentioned in this catalogue may be changed by Stucchi at any time, without notice; always refer to the version uploaded on the English version of stucchigroup.com/en website for the latest release. In case of doubt, please contact Stucchi technical service