M IRBO18 NPT

Codice articolo: **804501101 / ???????**

??????? ?????????? ?????? (POPPET)	**?????? ??????????** 1/8"
?????????? FKM (VITON)	**????????????????????** ISO 7241 B
??????? ?????????? ????? ???????????? ???????? ? ??????	**??????? ????????????** ????? ???????????? ????????
???????? ??????	**???????? ??????????** ????????????? ???
???????????? ??? ????????? ???	**P??????** FEMALE THREAD NPT (ANSI B.1.20.1)
?????????? ? ?????????? ????????? ???	**???????????** -15 / +180 °C; +5 / +356 °F
??????? ?????????? ????????? ?????????????, ??????????????, ??????? ??????????????, HVAC/R, ?????????????, ????? ??? ????????? ?????????, ????? ??? ?????????, ??????, ?????????? ? ???????????????? ????????????????, ???????????? ?????, ???????????????? ?????, ??????????-???????????? ??????, ???????????? ??????, ????????? ??????????, ??????? ????????, ????????, ???????? ???????????? ??? ???????????? ???????, ??????????????????? ???????? ????????????, ??????????????????? ???????, ?????????????, ???????? ?????????, ????? ? ???	

?????????????????	IMPERIAL
ISO DN (mm)	5
???????????? ?????? (???/???)	1.59
???????????? ??????? ???????? - ?????????? (psi)	2900
??????? ???????? - ???????????? (????/??. ????)	2900
???????? ??????? - ????????? (????/??. ????)	14500
???????? ??????? - ???????????? (????/??. ????)	14500
???? ?????????? (???? ????)	16.875
???? ????????????? (???? ????)	7.875
?????? (??)	0.18

??????	IMPERIAL
?????? ??????? (A)	1/8"
????? ????? ?+? (????)	2,38
????? (????)	1,18
????????????? ??????? (????)	0,43
??? (????)	0,04

????????????? ???????

??? ????????	Tipologia	???????????? ????????
804501100	Femmina	F IRBO18 NPT

STUCCHI Quick Couplings Catalog - April 2021 - All right reserved.
Via della Lira Italiana, 397 24040 - Pagazzano (BG) Italy - Contact us
Texts, data and illustrations mentioned in this catalogue may be changed by Stucchi at any time, without notice; always refer to the version uploaded on the English version of stucchigroup.com/en website for the latest release. In case of doubt, please contact Stucchi technical service